

Incident Report - Draft

Equipment: Bandsaw 2, Workshop 2

10 Aug 2027, ~14:20 - guard interlock failed during use. No injury.

Machine withdrawn from service. Investigation ongoing.